

[illegible]

Inspection Report

Report No.: 131206-054-V1

Inspection Date: 24th Dec 2013

Supplier :

Inspector: Ken Tung

Inspection only for:	Inspection Result:
PO .XYA-120501 Item No. 401-01-054	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
U max Base	500pcs	100% inspection	29pcs	27pcs with unclear symbols on the side . 1pcs with painting on the inside . 1piece with poor finish	500pcs

Appearance Inspection :

No failure,

29pcs are picked out from the final products.

Dimension Inspection:

No failure , below measurement report for reference.

Leakage Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection , 29pcs are rejected for unclear symbols on the side.

Digital photo records :



1. Packing



2. Carton



3. Side Mark



4. Pallet



5. Product



6. Product



7 Product



8. item number



9. test



10. Defect-unclear symbols



11. Defect- painting on the inside



12. Defect- poor finish



13. Defect-poor label




14. Defect-Poor painting




15. Carton



16. Loading



17. Test



18. Measurement report. as attached

[illegible]