

## Inspection Report

**Report No.:** XYND-140512  
**Supplier :** XY-GLOBAL

**Inspection Date:** 5<sup>th</sup> Jun, 2014  
**Inspector:** Leo

|                                                           |                                   |
|-----------------------------------------------------------|-----------------------------------|
| Inspection only for:<br>PO . XYND-140512 Item No.30013467 | <u>Inspection Result:</u><br>PASS |
|-----------------------------------------------------------|-----------------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| 30013467    | 10000PCS      | 1% inspection | 0pcs         | No failure          | 10000pcs        |

**Appearance Inspection :**

No failure,

**Dimension Inspection:**

No failure , below measurement report for reference.

**Assembly Test:**

No failure

**Inspection Summary**

The inspection sample plan is 100% inspection.

**Digital photo records :**



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

[illegible]