

Inspection Date: 3th Apr, 2015
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY009	30000PCS	1% inspection	0pcs	No failure	30000pcs

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. report

[illegible]