

Inspection Date: 3th July, 2014
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY28	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product





深圳市真朴电子科技有限公司

XY Electronics Technology Co., Ltd

Product Name: XY-1000

Model: XY-1000

Version: 1.0

Project Name: XY-1000

Project No.: XY-1000

Project Date: 2023-10-27

Project Manager: XY-1000

Project Engineer: XY-1000

Project Tester: XY-1000

Project Description: XY-1000

Project Scope: XY-1000

Project Goals: XY-1000

Project Risks: XY-1000

Project Deliverables: XY-1000

Project Milestones: XY-1000

Project Budget: XY-1000

Project Status: XY-1000

Project History: XY-1000

Project Change Log: XY-1000

Project Approval: XY-1000

Project Sign-off: XY-1000

5. Product:

6. report

[illegible]