

Inspection Report

Report No.: XYKB-140520
Supplier : XY-GLOBAL

Inspection Date: 14th Jun, 2014
Inspector: Leo

Inspection only for: PO : XYKB-140520 Item No. XY72YM016	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM016	800PCS	1% inspection	0pcs	No failure	800pcs

Appearance Inspection :
No failure,

Dimension Inspection:
No failure , below measurement report for reference.

Assembly Test:
No failure

Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

									
1. Packing	2. Product								
									
3. Product	4 Product								
	XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co., Ltd <table border="1"> <tr> <td>Inspection Date: 14/06/2014</td> <td>Product Name: XY72YM016</td> <td>Inspection Item: XY72YM016</td> <td>Inspector: Leo</td> </tr> <tr> <td>Part Name: XY72YM016</td> <td>Lot No: 140520</td> <td>Inspection Result: PASS</td> <td>Customer Name: XY-GLOBAL</td> </tr> </table> Inspection Report 1. General Information 2. Inspection Results 3. Defects 4. Conclusion 5. Remarks	Inspection Date: 14/06/2014	Product Name: XY72YM016	Inspection Item: XY72YM016	Inspector: Leo	Part Name: XY72YM016	Lot No: 140520	Inspection Result: PASS	Customer Name: XY-GLOBAL
Inspection Date: 14/06/2014	Product Name: XY72YM016	Inspection Item: XY72YM016	Inspector: Leo						
Part Name: XY72YM016	Lot No: 140520	Inspection Result: PASS	Customer Name: XY-GLOBAL						
5. Product:	6. Dimensions report:								

[illegible]