

Inspection Date: 27th Jun, 2013
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL017	18000PCS	5% inspection	Opes	No failure	18000pcs

The inspection sample plan is 100% inspection.

A large stack of cardboard boxes, secured with yellow straps, sitting on a wooden pallet. The boxes are arranged in a grid pattern, and the straps are used to hold them together. The background shows an industrial setting with a concrete floor and some equipment.



2. Product



4 Product

[illegible]

6. The test report

[illegible]