

Inspection Report

Supplier : XY-GLOBAL

Inspector: Leo

Inspector: Leo

Inspection only for: PO . XYKB-140518 Item No. XY72YM014	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM014	2000PCS	1% inspection	0pcs	No failure	2000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

[illegible]

6. Dimensions report:

[illegible]