

Inspection Date: 15th July, 2014
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY37	30000PCS	1% inspection	Opcs	No failure	30000pcs

The inspection sample plan is 100% inspection.

A photograph showing a large stack of cardboard boxes on a wooden pallet in a warehouse. The boxes are stacked in multiple layers, with some boxes showing a logo. The background shows a wall with some papers or notices pinned to it.



2. Product



3. Product

4 Product

[illegible]

5. Product:

6. report

[illegible]