

Inspection Report

Report No.: XYDN-140614

Inspection Date: 11th July, 2014

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYDN-140614 Item No.200380	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
200380	3000PCS	1% inspection	0pcs	No failure	3000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product

[illegible]