

Inspection Report

Report No.: XYKB-140509
Supplier : XY-GLOBAL

Inspection Date: 4th Jun, 2014
Inspector: Leo

Inspection only for: PO : XYKB-140509 Item No. XY72YM005	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM005	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co., Ltd

Inspection Item	Inspection Method	Inspection Result	Inspection Date	Inspector
Appearance	Visual	OK	2014.06.04	Leo
Dimension	Caliper	OK	2014.06.04	Leo
Assembly	Hand	OK	2014.06.04	Leo
Function	Test	OK	2014.06.04	Leo
Storage	Visual	OK	2014.06.04	Leo
Transportation	Visual	OK	2014.06.04	Leo
Usage	Visual	OK	2014.06.04	Leo
Disposal	Visual	OK	2014.06.04	Leo
Recycling	Visual	OK	2014.06.04	Leo
Other	Visual	OK	2014.06.04	Leo

6. Dimensions report:

[illegible]