

□□□□ OEM □□□□ □□□□ □□□□ □□□□



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYK-130811
Supplier : XY-GLOBAL

Inspection Date:01th Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYK-130811 Item No.1322100	<u>Inspection Result:</u> PASS
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
13222100	20PCS	100% inspection	0pcs	No failure	20pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

