

Inspection Report

Report No.: XYKB-140508

Supplier : XY-GLOBAL

Inspection Date: 4th Jun, 2014

Inspector: Leo

Inspection only for:	Inspection Result:
PO . XYKB-140508 Item No. XY72YM004	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM004	15000PCS	1% inspection	0pcs	No failure	15000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

A stack of four cardboard boxes, each labeled "XY-GLOBAL". The boxes are stacked vertically, with the top box clearly visible. The background shows more boxes and a green plant.

1. Packing

A close-up photograph of a dark, circular electronic component with a square cutout in the center. The component has a textured, possibly metallic or plastic, surface.

2. Product

A close-up photograph of the same dark, circular electronic component from a different angle, showing the square cutout and the surrounding structure.

3. Product

A close-up photograph of the same dark, circular electronic component from another angle, highlighting the square cutout and the component's profile.

4 Product

A close-up photograph of the same dark, circular electronic component, showing the square cutout and the component's structure from a slightly different perspective.

5. Product:

A detailed inspection report for XY Electronics Technology Co., Ltd. The report includes a header with the company name and logo, followed by a table of inspection data. The table has columns for Item, Quantity, Defect Type, Defect Description, and Defect Count. The data shows 15,000 units inspected with 0 defects found. The report is signed by Leo, dated Jun 4, 2014, and includes a signature of the inspector.

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Version:	XYKB-140508	Inspection Type:	100% Inspection	Inspection Date:	Jun 4, 2014
Part:	XY72YM004	Inspector:	Leo	Customer Name:	XY-GLOBAL
Qty:	15000	Inspection Result:	PASS	Inspection Time:	10:00-11:00
XY Electronics Technology Co., Ltd. is a professional manufacturer of various electronic components. The inspection results are as follows:					
Item	Quantity	Defect Type	Defect Description	Defect Count	
1. Appearance	15000	0	No defect found	0	
2. Dimension	15000	0	No defect found	0	
3. Assembly	15000	0	No defect found	0	
4. Function	15000	0	No defect found	0	
5. Reliability	15000	0	No defect found	0	
6. Safety	15000	0	No defect found	0	
7. Environmental	15000	0	No defect found	0	
8. Others	15000	0	No defect found	0	
Total	15000	0	No defect found	0	

XY Electronics Technology Co., Ltd. is a professional manufacturer of various electronic components. The inspection results are as follows:

Item	Quantity	Defect Type	Defect Description	Defect Count
1. Appearance	15000	0	No defect found	0
2. Dimension	15000	0	No defect found	0
3. Assembly	15000	0	No defect found	0
4. Function	15000	0	No defect found	0
5. Reliability	15000	0	No defect found	0
6. Safety	15000	0	No defect found	0
7. Environmental	15000	0	No defect found	0
8. Others	15000	0	No defect found	0
Total	15000	0	No defect found	0

XY Electronics Technology Co., Ltd. is a professional manufacturer of various electronic components. The inspection results are as follows:

Item	Quantity	Defect Type	Defect Description	Defect Count
1. Appearance	15000	0	No defect found	0
2. Dimension	15000	0	No defect found	0
3. Assembly	15000	0	No defect found	0
4. Function	15000	0	No defect found	0
5. Reliability	15000	0	No defect found	0
6. Safety	15000	0	No defect found	0
7. Environmental	15000	0	No defect found	0
8. Others	15000	0	No defect found	0
Total	15000	0	No defect found	0

6. Dimensions report:

[illegible]