

Inspection Report

Report No.: XYNK-130813

Supplier : XY-GLOBAL

Inspection Date: 15th Sep., 2013

Inspector: LEO

Inspection only for: PO : XYNK-130813 Item No. 7028190	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
7028190	5000PCS	100% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

