

Inspection Report

Report No.: XYKB-140514
Supplier: XY-GLOBAL

Inspection Date: 11th Jun, 2014
Inspector: Leo

Inspection only for: PO: XYKB-140514 Item No. XY72YM010	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM010	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection:
No failure,
Dimension Inspection:
No failure, below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records:

1. Packing

2. Product

3. Product

4 Product

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Client: XY	Product Name: XY72YM010	Inspection Date: 2014.6.11	Inspector: Leo
Part No: XY72YM010	Lot No: XY72YM010	Inspection Time: 10:00-12:00	Inspection Place: XY-GLOBAL
Inspection Method: 100%	Inspection Result: PASS	Inspection Status: OK	Inspection Report: XY72YM010
XY-GLOBAL XY72YM010 PLANK 100% 10			

[illegible]