

Inspection Report

Supplier : XY-GLOBAL

Inspector: Leo

Inspector: Leo

Inspection only for:	<u>Inspection Result:</u>
PO . XYAK-150416 Item No. XY31AL013	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31AL013	20000PCS	1% inspection	Opcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

[illegible]

6. report

Our sales team

