

Inspection Date: 10th July, 2014
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY014	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. report

1. Name: 2. Process: 3. Material: 4. Surface 5. Tolerance: 6. .Quality: 7.Specification: 8. 9. 10. 11.	1. Name: 2. Process: 3. Material: 4. Surface 5. Tolerance: 6. .Quality: 7.Specification: 8. 9. 10. 11.
--	--