

**Inspection Report**

**Report No.:** XYF-130819  
**Supplier :** XY-GLOBAL



**Inspection Date:** 11<sup>th</sup> Sep-, 2013  
**Inspector:** LEO

Inspection only for: PO . XYF-130819      Item No. screw cap	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
screw cap	<b>8000Set</b>	100% inspection	0pcs	No failure	8000Set

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

**Digital photo records :**

	
<p>1. Packing</p>	<p>2. Product:</p>
	
<p>3. Product:</p>	<p>4. Product:</p>
	
<p>5. Product :</p>	<p>6. inspection reports</p>

