

Inspection Report

Report No.: XYNK-130802
Supplier : XY-GLOBAL

Inspection Date: 1st Sep., 2013
Inspector: LEO

Inspection only for: PO : XYNK-130802 Item No.400-10-030	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-10-030	2000PCS	100% inspection	0pcs	No failure	2000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product:



3. Product:

4. Product:



5. Product :

6. Product:

[illegible]