

Inspection Report

Report No.: XYK-140720
 Supplier : XY-GLOBAL

Inspection Date: 9th Sep-, 2014
 Inspector: Alex

Inspection only for: PO . XYK-140720	Inspection Result: PASS
---	-----------------------------------


Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
140720	3000PCS	3% inspection	0pcs	No failure	3000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

