

Inspection Report


Report No.: XYK-140524
Supplier : XY-GLOBAL

Inspection Date: 20th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYK-140524 Item No.XY-141690	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-141690	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

[illegible]