

Inspection Report

Report No.: XYWD-140705
Supplier : XY-GLOBAL

Inspection Date: 28th July, 2014
Inspector: Leo

Inspection only for: PO : XYWD-140705 Item No. XY31SY49	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY49	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Report Form

Order No.	XYWD-140705	Product Name	XY31SY49	Inspection Date	28/07/2014
Client	XY-GLOBAL	Inspector	Leo	Customer Name	XY-GLOBAL
Inspector	Leo	Supervisor		Customer Address	
Product Description	XY31SY49: A small electronic component with a cylindrical body and a threaded base.				
Inspection Method	Visual inspection, dimension measurement, and assembly test.				
Inspection Results	No failure found. The product meets the requirements.				
Remarks	The inspection sample plan is 100% inspection.				

6. report

[illegible]