

00000000 0000000000 00000000 0000 ADC12 0000 00000000 0000000000

Inspection Report

Report No.: XYS-130928
Supplier : XY-GLOBAL

Inspection Date: 25th Oct, 2013
Inspector: Leo

Inspection only for: PO . XYS-130920 Item No.3240100	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
3240100	3000PCS	5% inspection	0pcs	No failure	3000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

[illegible]