

Inspection Report

Report No.: XYCY-150318
Supplier : XY-GLOBAL

Inspection Date: 14th Apr, 2015
Inspector: Leo

Inspection only for: PO : XYCY-150318 Item No. XY31CY020	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY020	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing 	2. Product 
3. Product 	4 Product  
5. Product:	6. report

[illegible]