

Inspection Report

Report No.: XYF-130814

Supplier : XY-GLOBAL


Inspection Date: 6th Sep-, 2013

Inspector: LEO

Inspection only for: PO . XYF-130814 Item No. screw	<u>Inspection Result:</u> PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
screw	10000Set	100% inspection	0pcs	No failure	10000Set

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. inspection reports

