

Inspection Report

Report No.: XYF-130818

Supplier : XY-GLOBAL

Inspection Date:10th Sep-, 2013

Inspector:LEO

Inspection only for: PO . XYF-130818 Item No. long screw	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
long screw	15000Set	100% inspection	0pcs	No failure	15000Set

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

podmis									
Inspection Report									
Report No: XYF-130818									
Inspector: LEO									
Item No: long screw									
Quantity: 15000Set									
Sample Size: 100%									
Defect Found: 0pcs									
Defects Description: No failure									
Acceptable Q'ty: 15000Set									
Assembly Test: No failure									
Inspection Summary: The inspection sample plan is 100% inspection.									

6. inspection reports

[illegible]