

Inspection Report

Report No.: XYKB-140512

Inspection Date: 8th Jun, 2014

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO : XYKB-140512 Item No. XY72YM008	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM008	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司

Inspection Report	Product Name	Inspection Date	Inspector	Page 5 of 5
XY72YM008	XY72YM008	2014.06.08	Leo	
Inspection Method	Inspection Result	Inspection Status	Inspection Date	Inspection Time
Visual Inspection	Pass	Pass	2014.06.08	10:00:00
Inspection Item	Inspection Result	Inspection Status	Inspection Date	Inspection Time
Dimensional Inspection	Pass	Pass	2014.06.08	10:00:00
Material Inspection	Pass	Pass	2014.06.08	10:00:00
Surface Inspection	Pass	Pass	2014.06.08	10:00:00
Functionality Inspection	Pass	Pass	2014.06.08	10:00:00
Assembly Inspection	Pass	Pass	2014.06.08	10:00:00
Storage Inspection	Pass	Pass	2014.06.08	10:00:00
Transportation Inspection	Pass	Pass	2014.06.08	10:00:00
Usage Inspection	Pass	Pass	2014.06.08	10:00:00
Disposal Inspection	Pass	Pass	2014.06.08	10:00:00
Recycling Inspection	Pass	Pass	2014.06.08	10:00:00
Other Inspection	Pass	Pass	2014.06.08	10:00:00

6. Dimensions report:

[illegible]