

Inspection Report

Report No.: XYWD-140601

Supplier : XY-GLOBAL

Inspection Date: 2nd July, 2014

Inspector: Leo

Inspection only for: PO : XYWD-140601 Item No. XY31SY22	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY22	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Report

Product Name: XY31SY22 Inspection Date: 2014.07.02 Inspected By: Leo

PO: XYWD-140601 Item No: XY31SY22 Quantity: 10000PCS

Inspection Item: 1. Appearance 2. Dimension 3. Assembly

Inspection Result: 1. Appearance: 0 Defects 2. Dimension: 0 Defects 3. Assembly: 0 Defects

Inspector: Leo Date: 2014.07.02

5. Product:

6. report

[illegible]