

0000000000 00 000000 000000 000000 000 applied 00000000 00 0000 000

Inspection Report

Report No.: XYS-130315
Supplier : XY-GLOBAL

Inspection Date: 12th Apr, 2013
Inspector: Leo

Inspection only for: PO . XYS-130315 Item No.XY-1300270	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1300270	1000PCS	5% inspection	0pcs	No failure	1000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

[illegible]