

Inspection Report

Report No.: XYGA-150321

Supplier : XY-GLOBAL

Inspection Date: 23th Apr-, 2015

Inspector: LEO

Inspection only for: PO . XYGA-140321 Item No. XY21ZC058	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC058	10000pcs	7% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



3. Product:



5. Product :



2. Product:



4. Product:

[illegible]

[illegible]