

Inspection Report

Report No.: XYSK-140612

Supplier : XY-GLOBAL

Inspection Date: 5th- July, 2014

Inspector: Leo

Inspection only for: PO . XYSK-140612 Item No. XY31SY012	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY012	18000PCS	1% inspection	Opes	No failure	18000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. report

[illegible]