

Inspection Report

Report No.: XYN-140616
Supplier : XY-GLOBAL

Inspection Date: 11th July, 2014
Inspector: Leo

Inspection only for:	Inspection Result:
PO . XYN-140616 Item No.142078	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
142078	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

6. Report:

[illegible]