

□□□□ □□□□□□ CNC □□□□



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYK-130817

Inspection Date: 15th Sep-, 2013

Supplier : XY-GLOBAL

Inspector: LEO

Inspection only for:	Inspection Result:
PO . XYK-130817 Item No.1305970	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1305970	3000PCS	3% inspection	0pcs	No failure	3000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing

2. Product:



3. Product:

4. Product:



5. Product :

6. Product:

[illegible]