

Inspection Report

Report No.: XYI-140903
Supplier : XY-GLOBAL

Inspection Date: 25th Sep, 2014
Inspector: Alex

Inspection only for: PO : XYI-140903 Item No. COIN_MASS_PRODUCTION	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
COIN_MASS_PRODUCTION	2000Set	100% inspection	0pcs	No failure	2000Set

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 32% inspection.

Digital photo records :



1. Packing

2. Packing



3. Product compared

4 Product compared



5. Product compared

6. Product compared



7. Product: OK

8. Product: OK

