

## Inspection Report

Report No.: XYK-140620  
Supplier : XY-GLOBAL

Inspection Date: 9<sup>th</sup> Aug-, 2013  
Inspector: Alex

|                                         |                                   |
|-----------------------------------------|-----------------------------------|
| Inspection only for:<br>PO . XYK-140620 | <u>Inspection Result:</u><br>PASS |
|-----------------------------------------|-----------------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| 140620      | 1000PCS       | 3% inspection | 0pcs         | No failure          | 1000pcs         |

**Appearance Inspection :**

No failure,

**Dimension Inspection:**

No failure , below measurement report for reference.


**Assembly Test:**

No failure

**Inspection Summary**


The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product:



3. Product:

4. Product:



5. Product :

6. Product:

