

Inspection Date: 12th July, 2014
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY33AH010	20000PCS	1% inspection	Opes	No failure	20000pcs

The inspection sample plan is 100% inspection.

A photograph of a pallet loaded with 20 cardboard boxes, secured with yellow straps. The boxes are arranged in two columns of ten, with a diamond-shaped logo on each. The pallet is on a dark floor, and a hand truck is visible in the background.



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. report

[illegible]