

Inspection Date: 10th July, 2014
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY015	10000PCS	1% inspection	Opes	No failure	10000pcs

The inspection sample plan is 100% inspection.

A stack of five cardboard boxes, each labeled "XY-GLOBAL", illustrating the concept of a stack data structure. The boxes are stacked vertically, with the top box being the most visible. A small plant is visible in the background to the right.



2. Product



4 Product

[illegible]

6. report

[illegible]