

SUS 440 〇〇〇〇〇〇 〇〇〇〇 〇〇〇



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYK-130827

Supplier : XY-GLOBAL

Inspection Date: 30th Sep-, 2013

Inspector: LEO

Inspection only for:	<u>Inspection Result:</u>
PO . XYK-130827 Item No.4542310	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
4542310	100PCS	100% inspection	0pcs	No failure	100pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

[illegible]