

Inspection Report

Report No.: XYDA-150306

Supplier : XY-GLOBAL

Inspection Date: 1st Apr, 2015

Inspector: Leo

Inspection only for:	Inspection Result:
PO : XYDA-150306 Item No. XY31CY025	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY025	23000PCS	1% inspection	0pcs	No failure	23000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing



2. Product



3. Product



4 Product



5. Product:



6. report

[illegible]