

Inspection Report

Report No.: XYFA-130804

Supplier : XY-GLOBAL

Inspection Date:1th Sep-, 2013

Inspector:LEO

Inspection only for: PO . XYFA-130804 Item No.400-01-069	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-01-069	5000pcs	100% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product :

[illegible]