

Inspection Report

Report No.: XYWD-140621

Supplier : XY-GLOBAL

Inspection Date: 15th- July, 2014

Inspector: Leo

Inspection only for: PO . XYWD-140621 Item No. XY31SY38	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY38	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

6. report

1.Name: 2.Process: 3.Material: 4.Surface 5.Tolerance: 0.01 -/+ 6 .Quality: 100 7.Specification: OEM 8. 9. 10. 11.	1.Name: 2.Process: 3.Material: 4.Surface 5.Tolerance: 0.01 -/+ 6 .Quality: 100 7.Specification: OEM 8. 9. 10. 11.
---	---