

Inspection Report

Report No.: XYWD-140605
Supplier : XY-GLOBAL

Inspection Date: 2nd July, 2014
Inspector: Leo

Inspection only for: PO . XYWD-140605 Item No. XY31SY25	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY25	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Customer Name	XY Electronics Technology Co., Ltd	Product Type	XY31SY25	Inspection Date	2014.07.02
Order No.	XYWD-140605	Lot No.	001	Inspector	Leo
Inspection Item	1. Appearance Inspection: 100% inspection. 2. Dimension Inspection: 100% inspection. 3. Assembly Test: 100% inspection.				
Inspection Result	1. Appearance: 0 defects. 2. Dimension: 0 defects. 3. Assembly: 0 defects. Overall: 0 defects.				
Inspector	Leo				

5. Product:

6. report

[illegible]