

Inspection Report

Report No.: XYDW-140621
Supplier: XY-GLOBAL

Inspection Date: 15th July, 2014
Inspector: Leo

Inspection only for: PO . XYDW-140621 Item No. XY33AH014	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY33AH014	32000PCS	1% inspection	0pcs	No failure	32000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Report	Product Type	Inspection Date
XY33AH014	XY33AH014	15/07/2014
Inspector	Inspector	Inspector
Leo	Leo	Leo

Inspection Result: PASS

Inspection Summary: No failure

Inspection Method: 100% inspection

Inspection Equipment: Vernier Caliper

Inspection Environment: 23±2°C, 50%±5% RH

Inspection Result: PASS

Inspector: Leo

Inspector Signature: [Signature]

Inspector Date: 15/07/2014

5. Product:

6. report

[illegible]