

Inspection Report

Report No.: XYWD-140616

Inspection Date: 10th July, 2014

Supplier: XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYWD-140616 Item No. XY31SY35	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY35	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Report Form

Product Name: XY31SY35 Part No: XY31SY35 Inspection Date: 10/07/2014

Inspector: Leo Customer: XY-GLOBAL

Inspection Result: PASS

Inspection Method: 100% Inspection

Inspection Location: XY Electronics Technology Co., Ltd

Inspection Equipment: Vernier Caliper

Inspection Results:

Item	Specification	Actual	Unit	Result
1	Dimension (mm)	10.0 ± 0.1	mm	PASS
2	Weight (g)	0.5 ± 0.05	g	PASS
3	Material	PC		PASS
4	Color	Black		PASS
5	Surface Finish	Smooth		PASS
6	Internal Structure	Complete		PASS
7	Electrical Properties	Good		PASS
8	Environmental Resistance	Good		PASS
9	Assembly Test	Good		PASS
10	Final Inspection	Good		PASS

Inspector: Leo Date: 10/07/2014

6. report

1.Name: 2.Process: 3.Material: 4.Surface 5.Tolerance: 0.01 -/+ 6 .Quality: 100 7.Specification: OEM 8. 9. 10. 11.	1.Name: 2.Process: 3.Material: 4.Surface 5.Tolerance: 0.01 -/+ 6 .Quality: 100 7.Specification: OEM 8. 9. 10. 11.
---	---