

Inspection Date: 10th July, 2014
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY36	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :	
No failure,	
Dimension Inspection:	
No failure , below measurement report for reference.	
Assembly Test:	
No failure	
Inspection Summary	
The inspection sample plan is 100% inspection.	

Digital photo records :



1. Packing

2. Product



3. Product

4 Product





XY-GLOBAL

深圳市真朴电子科技有限公司

XY Electronics Technology Co., Ltd

XY Electronics Technology Co., Ltd

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

XY-10000

5. Product:

6. report

[illegible]