

Inspection Report

Report No.: XYCY-150315

Supplier : XY-GLOBAL

Inspection Date: 10th Apr, 2015

Inspector: Leo

Inspection only for: PO : XYCY-150315 Item No. XY31CY017	Inspection Result: PASS
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY017	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Product Name: XYCY-150315
Product Type: XYCY-150315
Inspection Date: 2015-04-10
Inspector: Leo

Inspection Item: XYCY-150315
Inspection Method: 100% inspection

Inspection Result: PASS

Inspection Summary: The inspection sample plan is 100% inspection.

Inspection Details:

Item	1	2	3	4	5	6	7	8	9	10	11	12
1. Appearance												
2. Dimension												
3. Assembly												
4. Function												
5. Reliability												
6. Safety												
7. Environmental												
8. Others												

Inspection Conclusion: The inspection sample plan is 100% inspection.

Inspection Date: 2015-04-10
Inspector: Leo

5. Product:

6. report

[illegible]