

Inspection Report

Report No.: XYCY-150309

Inspection Date: 3rd Apr, 2015

Supplier: XY-GLOBAL

Inspector: Leo

Inspection only for:	Inspection Result:
PO: XYCY-150309 Item No. XY31CY011	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY011	18000PCS	1% inspection	0pcs	No failure	18000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co., Ltd												
Inspection Report												
Product Name	XYCY-150309					Product Type	XYCY-150309			Inspection Date	2015-04-03	
Part No.	XYCY-150309					Lot No.	XYCY-150309			Defect Rate	0%	
Inspector	Leo					Inspector	Leo			Defect Count	0	
Inspection Method: 100% Inspection												
Inspection Location: XY Electronics Technology Co., Ltd												
Inspection Equipment: XYCY-150309												
Inspection Results: 100% Pass												
Inspection Results: 100% Pass												

6. report

