

□□□□ □□□□□□□□ □□□□□□□□ A380 □□□□ □□□□ LED □□□□□□ □□□□

Inspection Report



Report No.: XYS-130717
Supplier : XY-GLOBAL

Inspection Date: 15th Aug, 2013
Inspector: Leo

Inspection only for: PO . XYS-130717 Item No.XY-2524960	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-2524960	1000PCS	5% inspection	0pcs	No failure	1000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

[illegible]