

Inspection Report

Report No.: XYD-140503
Supplier : XY-GLOBAL

Inspection Date: 5th Jun, 2014
Inspector: Leo

Inspection only for: PO : XYD-140503 Item No.XY-140223	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-140223	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:



7. Product:

A table representing the inspection report data. It has multiple columns and rows, with a header row containing 'pocdmis' and various inspection parameters. The table is filled with data, including numerical values and text descriptions.

8. Report:

[illegible]