

Inspection Report

Report No.: XYWD-140627
Supplier : XY-GLOBAL

Inspection Date: 25th July, 2014
Inspector: Leo

Inspection only for: PO : XYWD-140627 Item No. XY31SY44	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY44	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co., Ltd	
Inspection Date: 2014.07.25 Inspector: Leo	Product Name: XY31SY44 Drawing No: XY31SY44 Drawing Date: 2014.07.25 Drawing By: Leo
Inspection Item: 1. Appearance 2. Dimension 3. Function	Inspection Result: 1. Appearance: Pass 2. Dimension: Pass 3. Function: Pass
Inspection Method: 1. Visual inspection 2. Dimensional measurement 3. Functional test	Inspection Equipment: 1. Visual inspection 2. Dimensional measurement 3. Functional test
Inspection Result: 1. Appearance: Pass 2. Dimension: Pass 3. Function: Pass	Inspection Conclusion: 1. Appearance: Pass 2. Dimension: Pass 3. Function: Pass
Inspection Report: 1. Appearance: Pass 2. Dimension: Pass 3. Function: Pass	Inspection Report: 1. Appearance: Pass 2. Dimension: Pass 3. Function: Pass

5. Product:

6. report

[illegible]