

Inspection Report

Report No.: XYK-130825
Supplier : XY-GLOBAL

Inspection Date:19th Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYK-130825 Item No.1412790	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1412790	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing




2. Packing:




3. Product:



4. Product:



5. Product :



6. Product:

[illegible]